



1. **INTRODUCTION**

High purity un-stenched butane gas fitted with a universal adaptor.

SAS50 – 200ml Aerosol

2. **WHERE TO USE**

Ideal for re-filling gas lighters, torches, gas soldering irons, glue guns and other pieces of equipment designed to run off Butane/LPG.

3. **WHERE NOT TO USE**

- Anywhere other than that stated above.

4. **BENEFITS**

- High purity
- Low odour
- Fitted with universal refill adaptor.

5. **PHYSICAL PROPERTIES**

Appearance	Colourless gas, liquefied when under pressure.
pH	Not applicable
Specific Gravity	0.562
Non Volatiles % m/m	0
Active Content % m/m, as supplied	100
Flammability, as supplied	Extremely flammable, flash point below -20 C.
Composition Data, as supplied	A blend of butane, isobutene and propane.
Service Temperature (Continuous)	Designed for use at ambient temperatures.

6. **APPLICATION DETAILS**

Hold refill upside down over the device to be filled. Push the nozzle firmly into the device's refilling valve as far as it will go. Hold steady for 3 – 5 seconds or until full (generally indicated by escaping gas). Wait 30 seconds for any escaped gas to dissipate before igniting the device.